

Annexure D

BUILDING SAFETY CERTIFICATE

No. 102 / Comp AE-IV/25

Dated: 21.08.2025

It is certified that the existing building Parmeshwar Devi Dhanuka Saraswati Vidya Mandir Senior Secondary School (name of the building or premises) at Guvshala Nagar, Vrindawan, Mathura (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block A (1)	Block B (2)	Block C (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	2	3	2	X	X	X

The building is owned/occupied by Parmeshwar Devi Dhanuka Saraswati Vidya Mandir Sr. Sec. School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public works department (Name of Department/ Govt.) on 20/08/2025 (date of inspection) in the presence of Mr. Shivendra Gautam (Manager) (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 20/08/2025 for a period of 02 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. NIL
2. NIL
3. NIL
4. NIL

Issued on 20/08/2025 at Mathura by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

* The Certificate of Principal Architect Vipin Goyal Approved by MUDA L.No. 69/2016/47305 should be considered as the part of this Certificate. (Photocopy attached)

Signature with Seal: [Signature]
Name: Bijesh Kumar Sharma

Designation: Assistant Engineer

Name & Address of Department Office: CD-1 P.W.D., Mathura

66 | Page

[Signature]
(SHIVENDRA GAUTAM)

Manager
P.D. Dhanuka Saraswati Vidya Mandir
Senior Secondary School (Residential)
VRINDAVAN (MATHURA)

ATTESTED

[Signature]
PRINCIPAL

P. D. Dhanuka Saraswati Vidya Mandir
Senior Secondary School (Residential)
VRINDAVAN